


60

Figure 65

120

REVISIONS



EXPLANATION

Gulfco Marine Maintenance Site Boundary (approximate)



Monitoring Well Location -Zone A




Temporary Piezometer -Zone A

(0.037) 1,1-Dichloroethene (1,1-DCE) Concentration (mg/L) (Blue value for initial sample collected at each location (July 2006 - June 2007) Green value for samples collected November 2007 Red value for samples collected June 2008)

> Lateral Extent (defined by 0.7 mg/L concentration contour) Blue (July 2006 - June 2007) Green (November 2007) Red (June 2008)

Data Qualifier: J = Estimated value.



Source of photo: H-GAC, Texas aerial photograph, 2006.

GULFCO MARINE MAINTENANCE FREEPORT, BRAZORIA COUNTY, TEXAS


Figure 66

LATERAL EXTENT OF 1,1-DCE **CONCENTRATIONS IN ZONE A JULY 2006 THROUGH JUNE 2008**

題	PROJECT: 1352	BY: ZGK	REVISIONS
经	DATE: APRIL, 2011	CHECKED: EFP	

PASTOR, BEHLING & WHEELER, LLC

CONSULTING ENGINEERS AND SCIENTISTS



EXPLANATION

Gulfco Marine Maintenance Site Boundary (approximate)



Monitoring Well Location -Zone A




Temporary Piezometer -Zone A

(0.214) 1,2,3-Trichloropropane (1,2,3-TCP) Concentration (mg/L) (Blue value for initial sample collected at each location (July 2006 - June 2007) Green value for samples collected November 2007 Red value for samples collected June 2008)

> Lateral Extent (defined by 0.029 mg/L concentration contour) Blue (July 2006 - June 2007) Green (November 2007) Red (June 2008)

Data Qualifier: J = Estimated value.



Source of photo: H-GAC, Texas aerial photograph, 2006.

GULFCO MARINE MAINTENANCE FREEPORT, BRAZORIA COUNTY, TEXAS

Figure 67

LATERAL EXTENT OF 1,2,3-TCP CONCENTRATIONS IN ZONE A **JULY 2006 THROUGH JUNE 2008**

PROJECT: 1352	BY: ZGK	REVISIONS
DATE: APRIL, 2011	CHECKED: EFP	

PASTOR, BEHLING & WHEELER, LLC

CONSULTING ENGINEERS AND SCIENTISTS